

PRINT TIPS

- Condition stock in original packaging for a minimum of 24 hours at pressroom conditions. Ideal pressroom conditions are 70° to 75°F and 40 to 60% relative humidity (RH). Lack of conditioning may cause excessive curl, jamming and feeding issues, poor print quality and label delamination; check product temperature if these issues occur.
- Reference equipment instructions for machine settings. Use the following tips, as applicable:
 - Set to appropriate GSM and/or caliper or use the ‘heavyweight’ setting
 - For film facestocks, use the maximum amount of static elimination
 - For clear films, use the ‘white’ setting

If printing *paper* face stocks on a **KODAK NEXPRESS**,

- deliver sizes larger than 8.5 X 11 to the proof tray

- If a jam occurs, check for bent corners. If applicable, flip sheet to feed opposite side.